

# LIGHTING SYSTEM

6508V-01

## PRECAUTION

### 1. PRECAUTION OF HEADLIGHT BULB REPLACEMENT

- (a) When the halogen lamp (headlight and front fog light) surface is contaminated by oil, the lamp service life is shortened as it becomes hot when it is turned on.
- (b) Since the internal pressure of a halogen lamp bulb (headlight and front fog light) is high, carefully handle it as dropping a bulb may cause an explosion with jumping glass chips
- (c) When the lens are held with the bulb being removed for a long period of time, the lens may be contaminated by dirt or moisture. So being the work after preparing a new one when replacing a bulb.
- (d) Always use a replacement bulb having the same watt rating.
- (e) Firmly reinstall the socket after bulb replacement. Otherwise, cloudy lens or invasion by water will occur.