

**Introduction** A kit containing special foam sponge material has been developed. This kit, when used in conjunction with procedures outlined in the Wind Noise Service Information book (P/N 00401-42978), specific Service Tips and Technical Service Bulletins, should enable effective wind noise repairs.

**Affected Vehicles**

- All Models


**Parts  
Information**

PART NUMBER	PART NAME	SIZE (mm)	QTY
08231-00810	Kit, Wind Noise	---	1
08231-00811 *	Caulking Sponge Sealant No. 1	297 x 150 (T = 3.0)	2
08231-00812 *	Caulking Sponge Sealant No. 2	297 x 150 (T = 5.0)	2
08231-00813 *	Caulking Sponge Sealant No. 3	297 x 150 (T = 10.0)	2
08231-00814 *	Caulking Sponge Sealant No. 4	297 x 150 (T = 3.0)	2
08231-00815 *	Caulking Sponge Sealant No. 5	297 x 150 (T = 5.0)	2
08231-00816 *	Caulking Sponge Sealant No. 6	297 x 150 (T = 5.0)	2


\* All of these parts are included in the kit.

**Kit  
Components**


1. Caulking Sponge Sealant No. 1, No. 2 and No. 3 (Ept-sealer).



2. Caulking Sponge Sealant No. 4 and No. 5 (Ept-sealer). This sheet is divided into 27 strips, 5 mm wide.



3. Caulking Sponge Sealant No. 6 (Ept-sealer).



Index # **046556**