



Technical Service BULLETIN

April 24, 1998

Title: COWL TOP VENTILATOR LOUVER


Models:
'96 & '97 RAV4

BO009-98

BODY

Introduction To prevent snow from entering the cowl vent on 1996 and 1997 RAV4s, stainless steel mesh nets have been added to the cowl top ventilator louver.

Cowl Top Ventilator Louver -



Affected Vehicles • 1996 and 1997 RAV4.

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME
55708-42040	55708-42050	Louver Sub-Assembly, Cowl Top Ventilator

Warranty Information

OPCODE	DESCRIPTION	TIME	OPN	T1	T2
BD8003	R&R Cowl Top Ventilator Louver	0.5	55708-42040	66	57

Applicable Warranty*:

This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's complaint.

Repair Procedures

Replace the Cowl Top Ventilator Louver per the Repair Manual procedures.

Index • 049353



Toyota Supports ASE Certification