



# TOYOTA Technical Service BULLETIN

August 3, 2001

Title:

## FRONT BRAKE GROAN NOISE

Models:

'01 RAV4

RECEIVED  
BR007-01  
BRAKE

### TSB Revision Notice:

The image updated in this TSB is outlined in red.

**Introduction** New front brake pads are available to reduce the possibility of front brake groan noise.

**Applicable Vehicles**

- 2001 model year **RAV4** vehicles.

### Production Change Information

MODEL	STARTING VIN
RAV4 (2WD)	JTEGH20V#10035678
RAV4 (4WD)	JTEHH20V#10118762

### Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME
04465-42070	04465-42071	Pad Kit, Disc Brake

### Repair Procedure

If the customer encounters a front brake groan noise, replace the front brake pads (see 2001 RAV4 Repair Manual page BR-23, Pub. No. RM 797U2).

Repair of brake groan on this vehicle only requires replacement of the brake pads. If inspection reveals additional brake servicing is required, this can be performed per standard warranty policy and procedures.

### Warranty Information

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
473301	R & R Front Disc Brake Pad and/or Disc Brake Pad Shim (If needed for Groan Noise) (Both Sides)	0.8	04465-42070	91	99

### Applicable Warranty\*:

This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

\* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Toyota Supports ASE Certification

055555

Page 1 of 2

**Installation  
Procedure****Front Brake Pad Installation****NOTICE:**

- Make sure that pad A and pad B are correctly installed.
- Make sure to install the shims so that the arrow mark on the shim matches the direction of disc rotation.

