



# Technical Service BULLETIN

March 6, 1998

Title:

## FRONT AXLE HUB NUT REPLACEMENT

Models:

'92 - '98 Tercel, Paseo, Corolla, Celica, Camry  
'96 - '98 RAV4


DL001-98

DRIVELINE/DIFFERENTIAL

**Introduction** Due to a change of the friction control treatment on the nut thread, both types of Front Axle Hub Nuts (silver and black) for 1992 - 1998 Tercel, Paseo, Corolla, Celica, Camry and 1996 - 1998 RAV4s are **NOT reusable**.

### NOTE:

When replacing the Front Axle Hub Nut the new part must be the same color as the old part. When replacing a Silver nut -- use a NEW Silver nut and when replacing a Black nut -- use a NEW Black nut.



**Affected Vehicles**

- 1992 - 1998 Tercel, Paseo, Corolla, Celica, Camry and 1996 - 1998 RAV4s.

### Parts Information

| PART NUMBER | PART NAME     | COLOR  |
|-------------|---------------|--------|
| 90179-22020 | Nut, Axle Hub | Silver |
| 90178-22001 | Nut, Axle Hub | Black  |

### Warranty Information

| OPCODE | DESCRIPTION                | TIME | OPN | T1 | T2 |
|--------|----------------------------|------|-----|----|----|
| N/A    | Not applicable to warranty | -    | -   | -  | -  |

Index \* 049208



Toyota Supports ASE Certification