



Technical Service BULLETIN

February 16, 2001

Title:

STEERING WHEEL NUT SERVICE SPECIFICATION

Models:

All Applicable Models

ST001-01

STEERING

Introduction To make the steering wheel installation procedure similar for all models, the steering wheel nut tightening torque has been standardized.

Applicable Vehicles

MODEL		MODEL YEARS
TERCEL	EL42, 53	1991 – 1998
ECHO	NCP12	2000
PASEO	EL44, 54	1992 – 1997
COROLLA	AE10#, ZZE110	1993 – 2001
CELICA	AT180, ST18#, AT2#, ST2#, ZTZ23#	1990 – 2000
MR2	SW2#, ZZW30	1991 – 1995; 2000
CAMRY	SXV10, 20, MCV10, 20	1992 – 2000
CAMRY CNG	SXV23	2000 – 2001
CAMRY SOLARA	SXV20, MCV20	1999 – 2000
AVALON	MCX10, 20	1995 – 2000
SUPRA	JZA80	1993 1/2 – 1998
RAV4	SXA1#	1996 – 2000
RAV4 EV	BEA11	1998 – 2000
PREVIA	TRC10, 20	1991 – 1997
SIENNA	MCL10	1998 – 2000
HIGHLANDER	ACU20, 25, MCU20, 25	2001
4RUNNER	RN12#, 13#, VZN12#, 13#, 18#, RZN180, 185	1990 – 2000
LAND CRUISER	FZ80, FZJ80, UZJ100	1991 – 2000
TRUCK	RN8#, 9#, 10#, 110, VZN85, 9#, 10#, 110	1989 – 1995
TACOMA	RZN140, 150, 161, 171, 19#, VZN150, 160, 170, 195	1995 1/2 – 2000
T100	VCK10, 20	1993 – 1998
TUNDRA	VCK30, 40, UCK30, 40	2000

Warranty Information

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–



Toyota Supports ASE Certification

Index # 054588

Page 1 of 2

**Service
Information**