

SOUND QUALITY IS BAD ONLY WHEN CD IS PLAYED (VOLUME IS TOO LOW)

INSPECTION PROCEDURE

1	REPLACE CD WITH ANOTHER AND RECHECK
---	-------------------------------------

(a) Replace the CD with another and recheck.

(1) Check the installation condition of the radio receiver assembly.

OK: Malfunction disappears.

NG

**REPLACE RADIO RECEIVER ASSY
(SEE PUB. NO. RM864E, PAGE 67-2)**

OK

CD IS FAULTY