



**Technical Service  
BULLETIN**  
April 9, 1999

Title:

**REVISED DRIVE SHAFT GREASE**

Models:

**RAV4, Tercel, Corolla, Celica, Camry & Supra**

TC002-99

TRANSMISSION & CLUTCH

**Introduction** The greases supplied in replacement Inboard and Outboard Drive Shaft Boot Kits for the following models has been revised.

With this revision, the grease compositions have been changed and are now both the **same color**. To correctly lubricate each joint, consult the Service Repair Manual as to which **size** packet of grease is designated for each Drive Shaft Joint Assembly.

**NOTE:**

Although Inboard and Outboard greases are now the same color, their compositions are different.

**Affected  
Vehicles**

- All RAV4, Tercel, Corolla, Celica, Camry and Supra Models.

**Required  
Tools and  
Material**

As outlined in the Service Repair Manual.

**Repair  
Procedure**

Refer to the appropriate Repair Manual for installation and lubrication information for Drive Shaft Joint Assemblies.

**Warranty  
Information**

OPCODE	DESCRIPTION	TIME	OPN	T1	T2
N/A	Not Applicable to Warranty	-	-	-	-

Index # 051525



Toyota Supports ASE Certification