



Technical Service BULLETIN

November 16, 2001

Title:

REAR BRAKE SQUEAL NOISE

Models:

'01 – '02 RAV4

REVISED
BR009-01
BRAKES

TSB Revision Notice:

The information updated in this TSB is red and underlined.

Introduction New rear brake drums are available to reduce the possibility of rear brake squeal noise.

Applicable Vehicles

- 2001 – 2002 model year **RAV4** vehicles.

Production Change Information

MODEL	STARTING VIN
RAV4 (2WD)	JTEGH20V#20042534
RAV4 (4WD)	JTEHH20V#20130638
	JTEHH20V#26014721

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
42431-42011	42431-42050	Drum Sub-Assy, Rear Brake	2

Repair Procedure If the customer encounters a rear brake squeal noise, replace the rear brake drums.
(See the 2001 RAV4 Repair Manual, Pub. No. RM797U2, page BR-32.)

Warranty Information

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
472151	R & R Rear Brake Drum (One Side)	0.4	42431-42011	36	99
Combo A	Opposite Side	0.1			

Applicable Warranty*:

This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Toyota Supports ASE Certification

056048